



# Status of Opto-Boards Study

B. Cote, K.K. Gan, H. Kagan, C. Martin, Z. Pollock, S. Smith, B. Tar, C. Tandoi  
The Ohio State University

April 3, 2019



# Outline

- Introduction
- Study of 2013/14 opto-boards
- Study of irradiated opto-boards
- Future Plan



# Opto-Board Study Plan

- 2013/14 opto-boards:
  - 4 opto-boards operate with balanced data (40 MHz clock)
  - 4 opto-boards operate with 3  $\mu\text{s}$  burst of data every 10  $\mu\text{s}$ 
    - ◆ compare failure rate at 85 C/85% relative humidity to see if the burst mode causes more failures



# VCSEL/PIN Qualification Plan

- 2018 opto-boards:

- irradiation I:

- 4 Finisar and 4 ULM opto-boards

- ◆ 64 Finisar and 64 ULM VCSEL channels

- ◆ 32 Finisar and 32 ULM PIN channels

- irradiation II:

- 4 II-VI, 1 Finisar, 1 ULM opto-boards

- ◆ 32 II-VI VCSEL channels

- ◆ 8 Finisar and 8 ULM VCSEL channels

- target dose with 24 GeV protons:  $3 \times 10^{12}$  p/cm<sup>2</sup> for 200 fb<sup>-1</sup>

- ◆ received dose:  $\sim 3.8 \times 10^{13}$  p/cm<sup>2</sup>


- compare failure rate at 85 C/85% relative humidity to select vendor with less failures in 1,000 hours

# Opto-Boards in 85/85 Chamber





# 85/85 Test System



RX



# 2013/14 Opto-boards Test History


- 8 opto-boards were studied
  - ran for ~3 days at room temperature
  - one VCSEL array from two boards produce no optical power within few hours of operating at 85 C/85% RH
    - both arrays confirmed to have no power at QA system
    - no new failures after several days of testing at room temperature, 85 C, 85% RH
      - ⇒ resume operation at 85 C/85% RH
      - ⇒ one more array from one of the two boards failed few days later...
      - ⇒ VCSELs recovered if pressed on wire bond encapsulant
      - ⇒ VCSEL arrays detached at 85 C due to thermal stress
      - ⇒ both boards are labeled “second class” and “no opto-pack reinforcement” in database
      - ⇒ resume operation at 85/85



# Opto-Pack Reinforcement

Opto-pack

Aluminum brace




VDC  
(VCSEL driver)

DORIC  
(PIN receiver/decoder)






# Optical Power vs. Time (Burst)






# Optical Power vs. Time (Clock)





# Optical Power vs. Time (Burst)



- one channel has connection problem: receiving all “1”
  - VCSEL not dead!!




# Summary: 2013/14 Opto-Boards

- accumulated ~700 hours of operation at 85 C/85% RH
  - no VCSELs have died yet...




# Report on Irradiation II



- no VCSELs died during irradiation




# 85/85 Test on Irradiated Boards





# 85/85 Test on Irradiated Boards



- one channel has connection problem: receiving all “1”
- VCSEL not dead!!



# Summary: Irradiated Opto-Boards at 85/85

- accumulated ~100 hours of operation at 85 C/85% RH for 4 Finisar + 4 ULM opto-boards
  - 9 out 132 channels have connection problems but VCSELs not dead yet...
- 6 boards from irradiation II will be added this week





# Summary/Plan

- accumulated ~700 hours at 85C/85% RH for 2013/14 opto-boards
  - no VCSELs have died yet
- four II-VI opto-boards have been irradiated
  - good optical power at end of irradiation
- accumulated ~100 hours at 85C/85% RH for opto-boards from 1<sup>st</sup> irradiation
  - no VCSELs have died yet
- opto-boards from 2<sup>nd</sup> irradiation will be operated at 85 C/85% RH this week