

June 18, 2010




Outline

- Analysis of annealed VCSELs after irradiation
- Investigation of Optowell PINs leakage current problem
- Gathering storm on opto-boards of current pixel detector
- Summary




AOC 10 Gb/s VCSEL



Reasonable optical power for 6 arrays irradiated




Power Recovery Time vs Dosage



- Fit power vs time during annealing to exponential function
 - ⇒ recovery time increases with dosage
 - do not fully regain the lost power
 K.K. Gan
 IBL General Meeting




AOC 10 Gb/s VCSEL



- One channel produces no power
 - ⇒ need further investigation
- Power of several channels decrease with time
 - ⇒ need further investigation
- Plan to irradiate a sample of 20 arrays in August 2010



VCSEL Power vs Temperature



Ambient temperature VCSEL temperature is 8 C higher

- Cooler VCSEL produces more optical power
 - Same characteristic after irradiation and annealing





PIN Leakage Current Problem

- Three out of 20 irradiated Optowell PIN arrays are inoperable due to high leakage current
- Study of 7 unirradiated arrays:
 - ◆ temperature cycling at 0, 20, and 50 C up to 20 V bias voltage
 ⇒ no problem
 - ◆ temperature cycling at 0, 20, and 50 C up to 40 V bias voltage
 ⇒ no problem
 - temperature cycling at -25, 0, 20, and 50 C
 up to 40 V bias voltage is in progress
- No response from vendor regarding the problem
- Purchased 20 ULM arrays for irradiation in August 2010



TX Problem





- VCSEL arrays on off-detector TX of Pixel and SCT are dying at alarming rate in 2008
 - ⇒ replacement of all TXs in 2009
 - new TXs starts to die again in April 2010

Implication for IBL Opto-board

- VCSEL arrays on opto-boards of current pixel detector are identical to TX arrays
 - hypothesis: failure starts after some livetime
 - ⇒ expect failure on opto-board VCSEL arrays starting in ~2015
 - ⇒ may need to extract pixel package to replace all opto-boards
- Current plan for IBL opto-boards
 - use AOC 10 Gb/s VCSEL arrays instead of Truelight arrays
 - use BeO optical package instead of FR4 for heat removal
 - need to understand the current VCSEL problem to see to see if the above changes are sufficient
 - if opto-boards of current pixel detector need replacement
 - ⇒ will attempt to unify the design of all opto-boards



Summary

- VCSEL arrays have plenty of power after irradiation but there are two problems that need to be understood
 - will irradiate 20 AOC VCSEL arrays in August 2010
- 3 out of 20 Optowell PIN arrays broken
 - problem not yet understood
 - will irradiate 20 ULM PIN arrays in August 2010
- TX problem has major implication for current pixel detector and IBL
 - need to understand this problem to build reliable opto-links