



Lesson Learned from ATLAS Pixel Optical Link



Outline

- Introduction
- VCSEL/PIN monitoring
- Analysis of opto-board/VCSEL/PIN failures
- Summary




Introduction

- Architecture of ATLAS pixel optical links is similar to strip detector
 - ◆ use VCSEL/PIN arrays for on-detector optical links
 - ◆ 1744 TTC links
 - ◆ 1788 datalinks
 - ◆ 272 opto-boards



On-Detector PIN Current

- Monitoring of PIN current on opto-boards (on-detector) will tell us about the failures or radiation induced degradation




Actual failures much smaller.
See analysis later.



Off-Detector PIN Current

- Monitoring of PIN current on RXs (off-detector) will tell us about the failures or radiation induced degradation



Actual failures much smaller.
See analysis later.



Summary of Failures

- ~44 out of 1744 pixel modules are dead
 - ◆ HV, shorts/dead/noisy on FE's, opto failures...
 - ◆ opto failures account for ~1/3 of the problems



Opto-board Failure

- One opto-board (out of 272 boards) is inoperable
 - ⇒ six pixel modules are inoperable
 - ◆ failure cannot be on opto-board itself due to multiple connections between opto-board and VCSEL driver chips (VDC)
 - ⇒ a connection failure between opto-board and patch panel (PP2)
 - ⇒ need redundant and more robust connection between opto-board and PP2
 - new VDC on IBL:
 - power on reset circuit to set default VCSEL current to 10 mA



PIN Problem

- 9 pixel modules receive no clock or cannot be configured
 - ◆ 2 opto-board channels have no PIN current
 - ⇒ cold solder between PIN and opto-board
 - ⇒ replace the challenging micro soldering by wire bonding with new opto-pack design in IBL
 - ◆ the other 7 failures are probably due to a connection failure between opto-board and FE module control chip (MCC)
 - type0 cables are fragile



VCSEL Problem

- 5 pixel modules send no light to off-detector
 - ◆ cold solder between VCSEL and opto-board or ESD dead
 - ⇒ replace the challenging micro soldering by wire bonding with new opto-pack design in IBL
 - ◆ one of the dual data links for the innermost layer (B-layer) has the same problem
 - ⇒ must send all data out in one link



Summary

- Opto failures probably account for $\sim 1/3$ of the total failures
- Need redundant/more robust connection for VCSEL current control
 - ◆ propose to implement power on reset circuit to set default VCSEL current to 10 mA for IBL
- Opto-pack redesigned to use wire bonding instead of micro soldering for IBL
- Propose to implement redundancy for IBL