



Analysis of the Failures in the On-Detector Opto-Links of ATLAS Pixel

K.K. Gan
The Ohio State University

August 19, 2010




Outline

- Introduction
- Status of PIN arrays
- Status of VCSEL arrays
- Analysis of Failures
- Summary



ATLAS Pixel Opto-link



VCSEL: Vertical Cavity Surface Emitting Laser diode

VDC: VCSEL Driver Circuit

PIN: PiN diode

DORIC: Digital Optical Receiver Integrated Circuit



Status of On-Detector Opto-Links

- ~49 of 1744 pixel modules cannot be properly operated:
 - ◆ high or low voltage shorts
 - ◆ dead, shorted, or noisy front-end (FE) chips
 - ◆ 20 optical link related “failures”
 - how many of these actually opto failures?
 - date of last “failure”: June 2010



PIN Array Problems

- 10 pixel modules receive no clock or cannot be configured
 - ◆ 7 PIN channels on opto-boards have currents
 - will discuss later possible cause of failure
 - ◆ 2 PIN channels on opto-boards have no current
 - ⇒ most likely due to a cold solder between the PIN array optical package (opto-pack) and the opto-board
 - soldering micro leads to opto-board is very challenging
 - difficult to supply sufficient heat to leads due to excellent conductivity of BeO board
 - difficult to clean flux used in soldering
 - ⇒ cold solder masked by flux
 - ⇒ new opto-packs will use wire bonds for connection
 - ◆ 1 PIN channel has no current information



VCSEL Array Problems

- 10 pixel modules: no operating point for the off-detector opto-electronics to properly receive the data from the modules
 - ◆ 2 channels: light output not yet measured
 - ◆ 7 channels have no light
 - cold solder?
 - expect equal contribution to PIN failures:
 - 2 PIN channels have no current
 - ESD?
 - TX type failure?
 - a breakage in the electrical cable?
 - ◆ 1 channel has light



Type-0 Cables

- opto-board is connected to pixel modules using Type-0 cables
- ◆ pixel modules on outer layer use old, less reliable cables
 - ⇒ look for correlation between opto “failures” and cables:
 - old cables: $12/594 = (2.02 \pm 0.58)\%$
 - new cables: $4/1194 = (0.34 \pm 0.17)\%$
 - ⇒ failure rate associated with the old cables is much higher
 - ⇒ many opto “failures” might actually be broken electric connections in the Type-0 cables



TX Problem and Opto-board VCSELs

- VCSEL arrays on opto-boards of current pixel detector were fabricated using the same process as the TX arrays
 - ◆ current accumulated live time ~ 0.05 months
 - ◆ TXs start to fail after 6 months of live time
 - ⇒ expect failures on opto-board VCSEL arrays in the future



Lifetime Test of Truelight VCSEL

- Siegen is performing test of four opto-boards
 - ◆ transmitting clock (50% duty cycle) at room temperature
 - Wuppertal will measure optical spectrum monthly
- similar study of 7-8 boards planned on test system at CERN
 - ◆ transmitting clock at all times



Lifetime Test of Truelight VCSEL

- Ohio State has found ~50 VCSEL array from original production
 - ◆ 400 channels will be monitored
 - represent a significant fraction of final system: 1,788 channels
 - no need to use thermal acceleration
 - ◆ ~50% have improperly cured epoxy
 - ◆ will mount VCSEL on BeO board to emulate detector environment
 - ◆ will transmit pseudo random data (50% duty cycle)
 - ◆ will keep chamber at $\sim 20^{\circ}\text{C}$ flushed with N_2
 - ◆ still waiting for funds from US to acquire optical spectrum analyzer (OSA) to monitor degradation of spectrum with time
 - ◆ if some VCSELs in opto-boards/opto-packs fail within 6 months
 - ⇒ need to extract pixel detector to replace opto-boards



Summary

- ~1% of on-detector opto-links of Pixel detector are not working
- Major contributors to failures are probably:
 - ◆ Type0 cable problems
 - ◆ cold solders
- Failure rate is low so far
 - ◆ last failure: June 2010
- High statistics lifetime study of old VCSEL arrays planned