

Status of Opto-Boards

K.K. Gan

The Ohio State University

September 28, 2004

K. Arms, K.K. Gan, M.O. Johnson, H.P. Kagan, R.D. Kass,
A. Rahimi, C Rush, R. Ter-Antonian, M. Zoeller
The Ohio State University

A. Ciliox, M. Holder, M. Ziolkowski
Siegen University

Outline

- Improvements in Assembly Procedure
- Changes in Opto-board Layout
- Results from Irradiated Opto-boards
- Summary

Problems in Opto-Board Assembly

- soldering of opto-pack leads to opto-board:
 - ◆ use jig to transfer heat to all leads simultaneously
 - ◆ occasional cold solder joints and detachment of leads inside opto-pack
 - ◆ adjustment of high-temperature Teflon jig for each opto-board
- wire bonding:
 - ◆ low pull strength due to inadequately cleaned surfaces and not optimized bonding parameters
 - ⇒ occasional opto-board failure after burn-in/thermal cycle
 - ⇒ one channel in spare opto-board failed intermittently during annealing after ~ 30 Mrad

Improvements in Opto-pack Soldering

- solder one lead at a time with modified soldering tip:
 - file tip off at an angle
 - engrave a groove of rectangular cross section to increase contact area for heat transfer
 - trim the blunter tip to avoid contact with adjacent leads
 - achieve repeatability using soldering jig with a bar as arm rest for soldering iron
 - ⇒ same soldering angle for consistent heat transfer
 - clean flux off with flux solvent (isopropyl) for ease of inspection of solder quality
 - ⇒ consistent good soldering with contact time < 15 s
 - ⇒ no detachment in 17 opto-packs (170 leads)

Improvements in Wire Bonding

- single opto-pack lead soldering requires no rework
⇒ cleaner wire bond area!
- re-optimize wire bonding parameters
- successfully fabricated two opto-boards with double bonds
 - good pull strength with a minimum of 7.5 gmf

Improvements in Chip Masking

- chips are masked to prevent contamination from flux
- weak UV light source causes oxygen inhibition in mask curing
 - ⇒ mask not fully cured
 - ⇒ mask residues remain after mask was peeled
 - ⇒ lower wire bond quality
 - ⇒ strong UV light source on order

Connector Alignment Jig

- alignment holes for the 80-pin connector on new opto-boards could be under or over-sized
 - ⇒ connector jigs must be prepared as a fall-back solution
 - 2 out of 3 jigs passed assembly test on 5 opto-boards at assembly vendor
 - 5 more jigs were fabricated
 - ⇒ 2 passed measurement at OSU
 - ⇒ now at assembly vendor await testing on new opto-boards


Status of Opto-Board Production

- 4 boards produced and passed QA with new assembly procedure
⇒ no rework required!
- 1 opto-board has been burned in and currently in thermal cycle
- 2 opto-boards have opto-packs soldered and ready for wire bonding
⇒ yield = 100% based on 4 boards
- previous yield = 50% based on 10 boards produced with trials of various assembly procedures

Status of New Opto-Board Production

- several SMDs fell off in 3 out of 28 prototype opto-boards
 - ⇒ remove wire-bondable gold underneath solderable gold
 - ⇒ expect to improve adhesion and solderability
- ordered all blank boards needed to shorten fabrication time
 - status: delivered
- 80 b-layer boards with design changes were ordered
 - status: shipped yesterday (Monday)
 - ⇒ assemble 10 boards for evaluation
 - ◆ could be ready to submit Layer 1/2/disk design in 3 weeks

Maximum VCSEL Current




- some new VCSELs require lower voltage to produce a given current
⇒ > 20 mA in VCSEL when driven by VDC

Results on Proton Irradiation

- 4 opto-boards were irradiated with 24 GeV protons at CERN
 - dosage: ~30 Mrad
 - expected lifetime dosage: ~20 Mrad


PIN Current Threshold vs Dosage



● PIN current thresholds for no bit errors remain constant


Proton Induced Bit Errors in PIN

- convert observed bit errors into bit error rate at opto-link location
- bit error rate decreases with increasing PIN current as expected
- bit error rate $\sim 3 \times 10^{-10}$ at 100 μA (1.4 errors/minute)
- DORIC spec: 10^{-11}
- ⇒ bit error dominated by particle induced PIN current



Optical Power vs Dosage

- irradiation procedure: ~ 5 Mrad/day (10 hours)
with the rest of day annealing
- optical power decreases
with dosage as expected
- limited annealing
recovers some lost power
- still have good optical
power after 30 Mrad



Summary

- improved opto-board assembly procedure
⇒ much more reliable production
- CPT has produced 80 b-layer opto-boards
- VCSEL opto-packs on opto-boards
produce good power after 30 Mrad