

ScanPlus 1802

offline reset only - cordless scanner (full reset)




\40\02\46\42\60

RS-232 - baud rate - 9600 (*)



\40\01\41\07\60

RS-232 - data bits - 8



\40\01\43\60

RS-232 - parity - none




\40\01\46\00\60

RS-232 - stop bits - 1




\40\01\44\60

message length information - transmitted as 2 ASCII decimal digits




\40\01\4A\4B\0F\60

preamble - RS-232 - compose: LST



\40\01\45\53\2C\33\34\60

postamble - RS-232 - Carriage Return + Line Feed (*)



\40\01\45\54\3E\0D\3E\0A\60

UPC / EAN - active (*)



\40\02\41\56\60